DeMaria, Eva

From: DeMaria, Eva

Sent: Tuesday, December 01, 2015 3:59 PM

To: 'HOOD Robert'

Cc: Matt McClincy (mcclincy.matt@deq.state.or.us); Sheldrake, Sean; 'Scheffler, Linda';

LIVERMAN Alex (liverman.alex@deq.state.or.us); Michael Allen (allenmc@cdmsmith.com)

Subject: RE: Front LPTube Forgings Storm Water Source Control, ECSI #1239, Portland, OR

Attachments: EPA comments - Tube Forgings SWPCP 151201.pdf

Hi Rob-

Sorry this is so late. When I first received this, I saw that it was a Dec. 2014 document, so I left it alone for a while and then I thought it might be worthwhile to provide some comments. So here they are. Please call or email if you have questions. Thanks.

Eva

Eva DeMaria

Office of Environmental Cleanup | Superfund Site Cleanup Unit #2
U.S. EPA Region 10 | 1200 Sixth Avenue, Ste. 900, ECL-122 | Seattle, WA 98101
P: 206-553-1970 | demaria.eva@epa.gov

From: HOOD Robert [mailto:HOOD.Robert@deg.state.or.us]

Sent: Monday, September 28, 2015 1:29 PM **To:** DeMaria, Eva <DeMaria.Eva@epa.gov>

Subject: Front LPTube Forgings Storm Water Source Control, ECSI #1239, Portland, OR

Hello Eva. I am the new Project Manager for this Cleanup. Matt McClincy asked that I provide you the storm water pollution control plan. -Rob

Rob Hood
Natural Resources Specialist 4
Oregon DEQ
NW Region UST Cleanup & Environmental Cleanup Programs
700 NE Multnomah St., Suite #600
Portland, OR 97232
(503) 229-5617
hood.robert@deq.state.or.us

^{***}Note new address below.